ELLIOTTS =



Product Data Sheet

ArcSafe® T40 Arc Flash Switching Jacket

ATPV 40 PPE 4 Orange

The ArcSafe® T40 Arc Switching Jacket is made from orange Tencate Tecasafe Plus and has a Q8 thermal liner with an ATPV 40 PPE 4. This classic fabric system is inherently flame resistant and provides protection against electrical arc flashes and flash fires.

T40 Materials

- · Outer Fabric: Tencate Tecasafe Plus 251gsm
- · Lining Fabric: Q8 Thermal Liner 305gsm

Features

- · Classic T40 fabric system
- · Length 950mm

TAO Jacket

- Full 50mm hook + loop front closure
- · FR Knit Writers for extra protection
- · Bar tacking for extra strength
- · OPTIONAL: Added Reflective Trim: Class D/N



140 Jacket	with Reflective 171m	Size
EASCJT40SML	EASCJT40T1SML	SML
EASCJT40MED	EASCJT40T1MED	MED
EASCJT40LRG	EASCJT40T1LRG	LRG
EASCJT40XLG	EASCJT40T1XLG	XLG
EASCJT402XL	EASCJT40T12XL	2XL
EASCJT403XL	EASCJT40T13XL	3XL

with Doflactive Trim







Product Data Sheet

Standards and Certification

- This ArcSafe® Arc Flash protective garment has been independently tested by Kinectrics to:
 - ASTM F2621-06 Standard Practice for Determining Response Characteristics and Design Integrity of Arc Rated Finished Products in an Electric Arc Exposure.
- This garment with reflective trim added is certified to Australian Standard AS/NZS 4602.1:2011 High Visibility Safety Garments Class D/N by BSI.
- This garment is manufactured from materials conforming to AS/NZS 1906.4:2010 Retroreflective materials and devices for road traffic control purposes – High-visibility materials for safety garments.
- T40 Garments comply with ENA NENS 09-2014 National Guideline for the Selection, Use and Maintenance of PPE for Electrical Arc Hazards – Arc Rated Garments and Hoods.
- · Tecasafe Plus is UL Certified to NFPA 2112.
- T40 Fabrics meet the standards for NFPA70E and ASTM F1506.
- T40 Garments comply with AS4836:2011 Safe working on or near low-voltage electrical installations and equipment.





























IMPORTANT

NFPA 70E Compliance requires wearing of the whole system (3-piece) as ONE UNIT. 3 Pieces including hood, coat and leggings or hood, jacket and bib & brace trousers. Once a garment has been exposed to an arc flash, it must be removed from service.

